


CERTIFICATE/RECOMMENDATION

Visual inspection of Kendriya Vidyalaya Alwaye buildings have been carried out on 10 Aug 2019 and following points are observed :-

- (i) Roof leakage in primary block of building;
- (ii) Roof leakage in secondary block building;
- (iii) Leakage from chajja in Admin Block of building;
- (iv) Roof leakage in Admin block of building.

It is recommended roof treatment and chajja surface treatment are required for Kendriya Vidyalaya Alwaye School building also. It is certified that after visual inspection of the school building no cracks have been noticed in columns and beams. However the maintenance of buildings is carried out by KV Sangathan.

o/o AGE B/R Alwaye
NAD - PO
Alwaye - 63



Pradeep
(Pradeep Kumar Sharma)
AE (Civil)
AGE B/R Alwaye

13 Aug 2019

Repair and maintenance work is being carried out by CPWD, to clear the defect

Krishnaveni
जी. कृष्णावणी / KRISHNAVENI
प्राचार्य/Principal
केंद्रीय विद्यालय/Kendriya Vidyalaya
एन.ए.सी. कालमसरी / N.A.S. Kalamassery
एच.एम.टी. कॉलोनी पोस्ट/H.M.T. Colony P.O.
कालमसरी - 683 503/Kalamassery-683 503